

• General

- ✓ Sash width/height limits changed for Alujet 506/706
- ✓ Ventilation typologies available in S67/S77
- ✓ Handle 610-57-081-XX replaced by 610-78-010-XX/610-78-011-XX for shutter S325
- ✓ Crimp corner 113-57-224-00 replaced 490-77-882-00
- ✓ Uf values added in S77, M630, M9660

• Series S67/MD67

- ✓ Threshold option S67774 added with sash S67882

• Series S350/S350LT

- ✓ Flyscreen issue in 47mm/85mm typologies corrected
- ✓ S333 cuttings corrected

• Series M450

- ✓ M4566 cuttings corrected

• Series M14600

- ✓ Profiles M14640, M14639 added

• Series SF85

- ✓ S85030 cuttings corrected

• Series S77/SD77

- ✓ S77176 sash added in 2 sash typologies
- ✓ Glazing bead bridge 290-77-005-00 replaced by 290-77-003-00 in door typologies with S77582
- ✓ S77121 profile added to S77178 profile in easy access typologies
- ✓ Pivot typologies added

• Series S560LT

- ✓ 660-60-584-00 replaced by 660-30-582-00 in S30582 typologies

• Series M84FR

- ✓ New sash M84012 added

• Series M630

- ✓ M63118 cuttings corrected in subsill typologies

• Series S650

- ✓ S31733 stiffener added

• Γενικά

- ✓ Αλλαγή ορίων μηχανισμού Alujet 506/706
- ✓ Προστέθηκαν τυπολογίες εξαερισμού στην S67/S77
- ✓ Αντικαταστάθηκε το χερούλι 610-57-081-XX από το 610-78-010-XX/011-XX στα παντζούρια S325
- ✓ Αντικαταστάθηκε η γωνία 113-57-224-00 από την 490-77-882-00
- ✓ Προστέθηκαν τιμές Uf στις S77, M630, M9660

• Σύστημα S67/MD67

- ✓ Προστέθηκε το κατωκάσι S67774 στις τυπολογίες με φύλλο S67882

• Σύστημα S350/S350LT

- ✓ Διορθώθηκε το πρόβλημα με την σίτα στις 47mm/85mm τυπολογίες
- ✓ Διορθώθηκαν οι κοπές του S333

• Σύστημα M450

- ✓ Διορθώθηκαν οι κοπές του M4566

• Σύστημα M14600

- ✓ Προστέθηκαν τα προφίλ M14640, M14639

• Σύστημα SF85

- ✓ Διορθώθηκαν οι κοπές του S85030

• Σύστημα S77/SD77

- ✓ Προστέθηκε το φύλλο S77176 sash στις δίφυλλες τυπολογίες
- ✓ Αντικαταστάθηκε η γέφυρα τακαρίσματος 290-77-005-από την 290-77-003-00 στις πόρτες με προφίλ S77582
- ✓ Προστέθηκε το διακοσμητικό προφίλ S77121 στο S77178 στις easy access τυπολογίες
- ✓ Προστέθηκαν Pivot τυπολογίες

• Σύστημα S560LT

- ✓ Αντικαταστάθηκε το 660-60-584-00 από το 660-30-582-00 στις τυπολογίες με S30582 προφίλ

• Σύστημα M84FR

- ✓ Προστέθηκε το φύλλο M84012

• Σύστημα M630

- ✓ Διορθώθηκαν οι κοπές του M63118 σε τυπολογίες με subsill

• Σύστημα S650

- ✓ Προστέθηκε η ενίσχυση S31733