

- **General**
 - ✓ S67905 coupling added in M15000, M9400, M940, M11000, SD95, SD115
 - ✓ Anti lift hardware added in S560/S560 pocket, S560LT/S560LT pocket, S700/S700 pocket
 - ✓ Spring catch option added for PVC groove hardware added
- **Series MF65**
 - ✓ Reinforcement profile correctly positioned and cuttings corrected
 - ✓ M65130, M65135 cuttings corrected in even typologies
- **Series SD95**
 - ✓ 312-95-001-03 cuttings corrected
 - ✓ S95008 cuttings corrected
- **Series M450**
 - ✓ Drainage CNC machinings added in pocket typologies
 - ✓ Uf values added
- **Series M7**
 - ✓ Fapim 65kg typology limitations corrected
- **Series S650**
 - ✓ 770-09-399-00 silicon was replaced by 770-09-398-03
 - ✓ Front lock protection 640-65-009-00 replaced by 640-65-009-01
- **Series S77 FR**
 - ✓ New glazing bead S60455 available
- **Series S77**
 - ✓ S77996 cuttings corrected
 - ✓ Stepped phase doors added according to the catalogue
- **Series SF85**
 - ✓ S85032 cuttings corrected in buried sill typologies
- **Series M9660**
 - ✓ M19860 cuttings corrected in outwards opening door
 - ✓ New glazing bridge 290-19-620-00 added
- **Series M630**
 - ✓ 311-63-170-00/311-63-170-10 caps added in pocket typology
 - ✓ IFS flyscreen option added
- **Γενικά**
 - ✓ Η σύζευξη S67905 προστέθηκε στην M15000, M9400, M940, M11000, SD95, SD115
 - ✓ Το Anti Lift hardware προστέθηκε στην S560/S560 χωνευτά, S560LT/S560LT χωνευτά, S700/S700 χωνευτά
 - ✓ Ο συγκρατητής φύλλου προστέθηκε στα PVC hardware
- **Σύστημα MF65**
 - ✓ Διόρθωση της θέσης και των κοπών των προφίλ ενισχύσεων
 - ✓ Οι κοπές M65130, M65135 διορθώθηκαν στις ζυγές τυπολογίες
- **Σύστημα SD95**
 - ✓ Οι κοπές του 312-95-001-03 διορθώθηκαν
 - ✓ Οι κοπές του S95008 διορθώθηκαν
- **Σύστημα M450**
 - ✓ Προστέθηκαν κατεργασίες για τις απορροές στα χωνευτά
 - ✓ Προστέθηκαν Uf τιμές
- **Σύστημα M7**
 - ✓ Οι περιορισμοί για το hardware της Fapim 65kg διορθώθηκαν
- **Σύστημα S650**
 - ✓ Η σιλικόνη 770-09-399-00 αντικαταστάθηκε από την 770-09-398-03
 - ✓ Η προστασία μπροστινού κλειδώματος 640-65-009-00 αντικαταστάθηκε από την 640-65-009-01
- **Σύστημα S77 FR**
 - ✓ Νέο πηχάκι S60455 διαθέσιμο
- **Σύστημα S77**
 - ✓ Οι κοπές του S77996 διορθώθηκαν
 - ✓ Προστέθηκαν καβαλητές πόρτες σύμφωνα με τον κατάλογο
- **Σύστημα SF85**
 - ✓ Οι κοπές του S85032 διορθώθηκαν στις ενδοδαπέδιες τυπολογίες
- **Σύστημα M9660**
 - ✓ Οι κοπές M19860 διορθώθηκαν στις ανοιγόμενες έξω πόρτες
 - ✓ Η νέα γέφυρα τακαρίσματος 290-19-620-00 προστέθηκε
- **Σύστημα M630**
 - ✓ Οι τάπες 311-63-170-00/311-63-170-10 προστέθηκαν στα χωνευτά
 - ✓ Η σίτα IFS είναι διαθέσιμη